



PROJECT STATUS REPORT, 1st December 2017



Publishing Date: 1st December 2017

"Sun Valley", City Center Extension, Behind New Collectorate, Gwalior, MP, India. Ph. 0751-6004-222

TOWER A



TOWER B



TOWER C



TOWER D



TOWER E



TOWER F



TOWER G



TOWER H



TOWER I



TOWER J



TOWER K



TOWER L



TOWER M





	Work Status Report of Sun Valley as on 1st December 2017															
	Sr. No.	ITEM DESCRIPTION	TOWER (BLOCK)													
			A	B	C	D	E	F	G	H	I	J	K	L	M	CLUB AREA
FOUNDATION	PODIUM AREA (EXTENDED BASEMENT AREA)															
	1	Excavation for column footings	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	2	Trimming, Leveling	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	3	Termite treatment	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	4	PCC	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	5	RCC independent footings	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	6	RCC Columns	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	7a	Soil Filling	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
7b	RCC slab casting	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	
FOUNDATION	TOWER AREA															
	8	Termite treatment at foundation level	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	9	Excavation for Raft	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	10	PCC 1:4:8 for Raft	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	11	Reinforcement Of Raft Foundation	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	12	RCC Raft	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
BASEMENT	13	RCC Columns (up to plinth level)	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	14	Retaining Wall RCC	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	15 a	1st Slab (parking slab) reinforcement	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	15 b	1st Slab (parking slab) RCC casting	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	15 c	Internal Plastering in parking area	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
GROUND FLOOR																
	16 a	2nd Slab (Ground floor slab)	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	16 b	Brick Masonry wall in Ground floor	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	16 c	Electrical conducting (Wall chasing & Box Fixing)	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	16 d	Internal Plastering in Ground floor	100%		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	16 e	CPVC Work (Plumbing Line)	100%		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	16 f	PVC Work (Sanitary Line)	100%		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
FIRST FLOOR	17 a	3rd Slab (First floor slab)	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	17 b	Brick Masonry wall in First floor	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	17 c	Electrical conducting (Wall chasing & Box Fixing)	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	
	17 d	Internal Plastering in first floor		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	
	17 e	CPVC Work (Plumbing Line)		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	
	17 f	PVC Work (Sanitary Line)		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	



Work Status Report of Sun Valley as on 1st December 2017

	Sr. No.	ITEM DESCRIPTION	TOWER (BLOCK)													CLUB AREA
			A	B	C	D	E	F	G	H	I	J	K	L	M	
SECOND FLOOR	18 a	4th Slab (Second floor)	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	
	18 b	Brick Masonry wall in Second floor	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	
	18 c	Electrical conducting (Wall chasing & Box Fixing)		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	
	18 d	Internal Plastering in Second floor		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	
	18 e	CPVC Work (Plumbing Line)		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	
	18 f	PVC Work (Sanitary Line)		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
THIRD FLOOR	19 a	5th Slab (Third floor)	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	19 b	Brick Masonry wall in Third floor	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	19 c	Electrical conducting (Wall chasing & Box Fixing)		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	19 d	Internal Plastering in Third floor		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	19 e	CPVC Work (Plumbing Line)		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	19 f	PVC Work (Sanitary Line)		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
FOURTH FLOOR	20 a	6th Slab (Fourth floor)	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	20 b	Brick Masonry wall in Fourth floor	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	20 c	Electrical conducting (Wall chasing & Box Fixing)		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	20 d	Internal Plastering in Fourth floor		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	20 e	CPVC Work (Plumbing Line)		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	20 f	PVC Work (Sanitary Line)		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
FIFTH FLOOR	21 a	7th Slab (Fifth floor)	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	21 b	Brick Masonry wall in Fifth floor		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	21 c	Electrical conducting (Wall chasing & Box Fixing)		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	21 d	Internal Plastering in Fifth floor		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	21 e	CPVC Work (Plumbing Line)			100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	21 f	PVC Work (Sanitary Line)			100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
SIXTH FLOOR	22 a	8th Slab (Sixth floor)	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	22 b	Brick Masonry wall in Sixth floor		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	22 c	Electrical conducting (Wall chasing & Box Fixing)		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	22 d	Internal Plastering in Sixth floor		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	22 e	CPVC Work (Plumbing Line)			100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	22 f	PVC Work (Sanitary Line)			100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x

Work Status Report of Sun Valley as on 1st December 2017

	Sr. No.	ITEM DESCRIPTION	TOWER (BLOCK)													CLUB AREA
			A	B	C	D	E	F	G	H	I	J	K	L	M	
SEVENTH FLOOR	23 a	9th Slab (Seventh floor)	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	23 b	Brick Masonry wall in Seventh floor		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	23 c	Electrical conducting (Wall chasing & Box Fixing)		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	23 d	Internal Plastering in Seventh floor			100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	23 e	CPVC Work (Plumbing Line)			100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	23 f	PVC Work (Sanitary Line)			100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
EIGHTH FLOOR	24 a	10th Slab (Eighth Floor)		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	24 b	Brick Masonry wall in Eighth floor		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	24 c	Electrical conducting (Wall chasing & Box Fixing)		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	24 d	Internal Plastering in Eighth floor			100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	24 e	CPVC Work (Plumbing Line)			100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	24 f	PVC Work (Sanitary Line)			100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
NINTH FLOOR	25 a	11th Slab (Ninth floor)		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	25 b	Brick Masonry wall in Ninth floor		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	25 c	Electrical conducting (Wall chasing & Box Fixing)		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	25 d	Internal Plastering in Ninth floor		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	25 e	CPVC Work (Plumbing Line)			100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	25 f	PVC Work (Sanitary Line)			100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
TENTH FLOOR	26 a	12th Slab (Tenth/Top floor)		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	26 b	Brick Masonry wall		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	x
	26 c	Electrical conducting (Wall chasing & Box Fixing)		100%	100%	100%	100%	100%	100%	100%			100%	100%	100%	x
	26 d	Internal Plastering in Tenth floor		100%	100%	100%	100%	100%	100%	100%			100%	100%	100%	x
	26 e	CPVC Work (Plumbing Line)		100%	100%	100%	100%	100%	100%	100%						x
	26 f	PVC Work (Sanitary Line)			100%	100%	100%	100%	100%	100%						
ELEVENTH FLOOR	27 a	13th Slab (Eleventh floor)		100%	100%	x	x	x	x	x	x	x	x	x	x	x
	27 b	Brick Masonry wall		100%	100%	x	x	x	x	x	x	x	x	x	x	x
	27 c	Electrical conducting (Wall chasing & Box Fixing)		100%	100%	x	x	x	x	x	x	x	x	x	x	x
	27 d	Internal Plastering in Eleventh floor		100%	100%	x	x	x	x	x	x	x	x	x	x	x
	27 e	CPVC Work (Plumbing Line)		100%	100%	x	x	x	x	x	x	x	x	x	x	x
	27 f	PVC Work (Sanitary Line)			100%	x	x	x	x	x	x	x	x	x	x	x



	Work Status Report of Sun Valley as on 1st December 2017															
	Sr. No.	ITEM DESCRIPTION	TOWER (BLOCK)													
			A	B	C	D	E	F	G	H	I	J	K	L	M	CLUB AREA
TWELFTH FLOOR	28 a	14th Slab (Twelfth floor)		100%	100%	x	x	x	x	x	x	x	x	x	x	x
	28 b	Brick Masonry wall		100%	100%	x	x	x	x	x	x	x	x	x	x	x
	28 c	Electrical conducting (Wall chasing & Box Fixing)		100%	100%	x	x	x	x	x	x	x	x	x	x	x
	28 d	Internal Plastering in Twelfth floor		100%	100%	x	x	x	x	x	x	x	x	x	x	x
	28 e	CPVC Work (Plumbing Line)			100%	x	x	x	x	x	x	x	x	x	x	x
	28 f	PVC Work (Sanitary Line)			100%	x	x	x	x	x	x	x	x	x	x	x
THIRTEENTH FLOOR	29 a	15th Slab (Thirteenth floor)		100%	100%	x	x	x	x	x	x	x	x	x	x	x
	29 b	Brick Masonry wall		100%	100%	x	x	x	x	x	x	x	x	x	x	x
	29 c	Electrical conducting (Wall chasing & Box Fixing)			100%	x	x	x	x	x	x	x	x	x	x	x
	29 d	Internal Plastering in Thirteenth floor			100%	x	x	x	x	x	x	x	x	x	x	x
	29 e	CPVC Work (Plumbing Line)			100%	x	x	x	x	x	x	x	x	x	x	x
	29 f	PVC Work (Sanitary Line)			100%	x	x	x	x	x	x	x	x	x	x	x
COMMON WORK	30a	TOWER COMMON WORK														
	30b	LIFT-1				50%	50%							50%	50%	
	30c	LIFT-2														
	30d	OVER HEADWATER TANK		100%	100%	100%	100%	100%	100%	100%	50%	50%	100%	100%	100%	
	30e	ELECTRIC RISING MAIN				100%	100%							100%	100%	
	30f	FIRE RISING MAIN				100%	100%	100%	100%					100%	100%	
	30g	COMMON CORRIDOR				100%	100%	100%	100%					100%	100%	
	30h	WATER SUPPLY				100%	100%	50%	50%	50%				100%	100%	
	30i	ELECTRIC SUPPLY				100%	100%							100%	100%	

Work Status Report of Sun Valley as on 1st December 2017

S. No.	PROJECT COMMON WORK	STATUS
1	SEPTIC TANK	COMPLETED
2	UNDER GROUND WATER TANK 6 LAC CAPACITY	COMPLETED
3	PUMP HOUSE	COMPLETED
4	32 KVA ELECTRIC SUBSTATION	RUNNING
5	FRONT GARDEN	RUNNING
6	CENTRAL GARDEN	RUNNING
7	CLUB INTERIOR	RUNNING
8	SWIMMING POOL	RUNNING
9	KIDS PLAY AREA	RUNNING
10	BADMINTON COURT	RUNNING
11	BASEMENT FINISH	RUNNING
12	WATER HAVESTING PLANT (10)	COMPLETED
13	SEWER LINE	COMPLETED

SUNLIFE INFRATECH



THANK YOU

Corporate Office: T-14, Central Mal, Nr. Acheleshwar Temple, Lashkar, Gwalior, M.P., India. **Ph.:** 0751-2450-381 **Email:** info@sunvalleygwalior.com

"Sun Valley", City Center Extension, Behind New Collectorate, Gwalior, MP, India. Ph. 0751-6004-222